

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

HD1040  
East  
> 1  
1.350 mi.  
7127 ft.

IN BOILER ROOM  
110 SHORE BLVD  
BROOKLYN, NY  
Site 2 of 2 in cluster HD

NY AST  
NY Spills  
U003395729  
N/A

Relative:  
Higher

AST:

Actual:  
3 ft.

Name: 110 SHORE BLVD HOUSING CORPORATION  
Address: 110 SHORE BLVD  
City,State,Zip: BROOKLYN, NY 11235  
Region: STATE  
DEC Region: 2  
Site Status: Active  
Facility Id: 2-600723  
Program Type: PBS  
UTM X: 588560.84914  
UTM Y: 4492841.38118  
Expiration Date: 04/22/2022  
Site Type: Apartment Building/Office Building

Affiliation Records:

Site Id: 22703  
Affiliation Type: Facility Owner  
Company Name: 110 SHORE BLVD HOUSING CORP  
Contact Type: MANAGER  
Contact Name: KALIKA  
Address1: 40 RANDALL AVENUE  
Address2: Not reported  
City: FREEPORT  
State: NY  
Zip Code: 11520  
Country Code: 001  
Phone: (718) 968-2876  
EMail: Not reported  
Fax Number: Not reported  
Modified By: DMPOKRZY  
Date Last Modified: 2018-03-19

Site Id: 22703  
Affiliation Type: Mail Contact  
Company Name: PRINCIPAL MGMT  
Contact Type: Not reported  
Contact Name: ROMAN KALIKA  
Address1: 40 RANDAL AVENUE  
Address2: Not reported  
City: FREEPORT  
State: NY  
Zip Code: 11520  
Country Code: 001  
Phone: (718) 968-2876  
EMail: RKALIKA@DEPENDABLEPRO.COM  
Fax Number: Not reported  
Modified By: DMPOKRZY  
Date Last Modified: 2018-03-19

Site Id: 22703  
Affiliation Type: Facility Operator  
Company Name: 110 SHORE BLVD HOUSING CORPORATION  
Contact Type: Not reported  
Contact Name: FATON SYLA

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Address1: Not reported  
Address2: Not reported  
City: Not reported  
State: NN  
Zip Code: Not reported  
Country Code: 001  
Phone: (718) 968-2876  
EMail: Not reported  
Fax Number: Not reported  
Modified By: DMPOKRZY  
Date Last Modified: 2018-03-19

Site Id: 22703  
Affiliation Type: Emergency Contact  
Company Name: 110 SHORE BLVD HOUSING CORP  
Contact Type: Not reported  
Contact Name: KALIKA  
Address1: Not reported  
Address2: Not reported  
City: Not reported  
State: NN  
Zip Code: Not reported  
Country Code: 999  
Phone: (516) 223-8833  
EMail: Not reported  
Fax Number: Not reported  
Modified By: DMPOKRZY  
Date Last Modified: 2018-03-19

Tank Info:

Tank Number: 001  
Tank Id: 43453  
Material Code: 0001  
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

E00 - Piping Secondary Containment - None  
B00 - Tank External Protection - None  
F00 - Pipe External Protection - None  
A00 - Tank Internal Protection - None  
D01 - Pipe Type - Steel/Carbon Steel/Iron  
K00 - Spill Prevention - None  
L09 - Piping Leak Detection - Exempt Suction Piping  
C01 - Pipe Location - Aboveground  
I04 - Overfill - Product Level Gauge (A/G)  
G00 - Tank Secondary Containment - None  
J02 - Dispenser - Suction Dispenser  
H99 - Tank Leak Detection - Other

Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil,  
allowing no visual inspection.  
Tank Type: Steel/Carbon Steel/Iron  
Tank Status: In Service  
Pipe Model: Not reported  
Install Date: 01/01/1900  
Capacity Gallons: 5000  
Tightness Test Method: NN  
Date Test: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Next Test Date: Not reported  
Date Tank Closed: Not reported  
Register: True  
Modified By: DMPOKRZY  
Last Modified: 03/19/2018  
Material Name: #2 fuel oil (on-site consumption)

SPILLS:

Name: IN BOILER ROOM  
Address: 110 SHORE BLVD  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 1209456 / 2012-11-12  
Facility ID: 1209456  
Facility Type: ER  
DER Facility ID: 426776  
Site ID: 472520  
DEC Region: 2  
Spill Cause: Storm  
Spill Class: Not reported  
SWIS: 2401  
Spill Date: 2012-11-06  
Investigator: HRPATEL  
Referred To: Not reported  
Reported to Dept: 2012-11-06  
CID: Not reported  
Water Affected: Not reported  
Spill Source: Commercial/Industrial  
Spill Notifier: Other  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2012-11-06  
Spill Record Last Update: 2012-11-12  
Spiller Name: Not reported  
Spiller Company: HURRICANE SANDY  
Spiller Address: Not reported  
Spiller Company: 999  
Contact Name: PAUL FELDMAN  
DEC Memo: "case closed. refer to spill #: 1208211."  
Remarks: "water with oil in boiler room"

All Materials:

Site ID: 472520  
Operable Unit ID: 1222379  
Operable Unit: 01  
Material ID: 2221100  
Material Code: 0001A  
Material Name: #2 fuel oil  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: Not reported  
Units: Not reported  
Recovered: Not reported  
Oxygenate: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Name: 110 SHORE RD.  
Address: 110 SHORE ROAD  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 9206068 / 1992-08-25  
Facility ID: 9206068  
Facility Type: ER  
DER Facility ID: 79297  
Site ID: 86433  
DEC Region: 2  
Spill Cause: Other  
Spill Class: D4  
SWIS: 2401  
Spill Date: 1992-08-25  
  
Investigator: KSTANG  
Referred To: Not reported  
Reported to Dept: 1992-08-25  
CID: Not reported  
Water Affected: Not reported  
Spill Source: Vessel  
Spill Notifier: Federal Government  
Cleanup Ceased: 1992-08-25  
Cleanup Meets Std: True  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 1992-09-02  
Spill Record Last Update: 2004-09-30  
Spiller Name: Not reported  
Spiller Company: Not reported  
Spiller Address: Not reported  
Spiller Company: 001  
Contact Name: Not reported  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was  
TANG "  
  
Remarks: "33 CATURET CRUISER SANK, USCG ON SCENE CALLED USCG BACK NO BIG  
PROBLEMEVERYTHING UNDER CONTROL 5 PEOPLE SWAM TO SHORE THE BOAT SANK,  
THE GASOLINE TANK IS NOT LEAKING OWNER WILL TRY TO SAVE THE BOAT."  
  
All Materials:  
Site ID: 86433  
Operable Unit ID: 973313  
Operable Unit: 01  
Material ID: 557126  
Material Code: 0009  
Material Name: gasoline  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: 130.00  
Units: G  
Recovered: .00  
Oxygenate: Not reported